

USB cable revision history

Revision UC22 4/10/2003

Fix Japanese keys

The Ro and the Yen keys were not being received on Windows computers. This has been fixed.

Revision UC21 8/07/2002

Improve driving distance

Sometimes 35 foot or longer cables would give mouse errors. The mouse algorithm has been improved to give more margin.

Revision UC20 5/06/2002

Resolves Macintosh boot problems

Allows booting from a bootable CD-ROM by preventing CD-ROM ejection during the boot process. Eliminates "hard disk not found" errors when booting G4 Macintosh machines. Allows the user to rebuild the desktop and reset the Parameter RAM using Macintosh keyboard commands.

[More.](#)

Prevents keyboard failure at the Sun login screen

Fixes a bug which disabled the keyboard when the screen saver became active at the login screen.

Revision UC19 02/08/2002

Allows normal keyboard operation during Sun boot process

The keyboard now operates normally at the OpenBoot prompt when the environment autoboot flag is set to false. Typing Stop-A after power up now halts the autoboot process at the OpenBoot prompt.

Provides variable keyboard country code for Sun computers

The character set used by Sun Solaris depends on the USB keyboard's country code. Now the adapter cable can get its country code from supporting Rose switches. Support for this feature is found in multiplatform UltraView Pro with program version UPP18A or greater and in multiplatform UltraMatrix with program version MXP21D or greater. Switches without support for this feature will use the U.S. country code. You must pick the proper country in the Sun keyboard language setting on the Configure System page of the OSD in order for this feature to work.

Revision UC17 11/09/2001

Fixes Macintosh mouse problem

Corrects a problem with Macintosh mouse data which was introduced in version 16.

Revision UC16, UC16J, UC16K 10/22/2001

Add support for Sun special keys

Additions to the USB table allow the use of 14 Sun keys (e.g. Stop) when used with a supporting switch. This feature requires UltraView Pro with program version UPP18 or later, or UltraMatrix with program version MXP21B or later.

Correct repeating keystrokes on Sun computers

Corrects a bug which caused typed keys to be repeated intermittently during very rapid typing on a Sun computer.

Add support for Japanese and Korean special keys

USB table additions permit 6 Japanese and 2 Korean language keys to function correctly. If the KVM keyboard is Sun type 5 or 6, UltraView Pro with program UP18 or UltraMatrix with program MXP21B are required.

Corrects the F5 key assignment

Fix a bug which prevented the F5 key from functioning correctly.

Make Sun special versions for Sun Japan and Korea

Sun for USB table additions permit 6 Japanese and 2 Korean language keys to function correctly. If the KVM keyboard is Sun type 5 or 6, UltraView Pro with program UP18 or UltraMatrix with program MXP21B are required.